SkyTech Helicopters Ltd.

Tel: +44 (0) 1604 493137

E-mail: sales@skytechhelicopters.co.uk

1978 Bell 206 BIII





Skytech offer for immediate sale this beautifully refurbished Bell 206BIII Jetranger.

Airframe: - 3085 hours TTSN.

Many components recently overhauled.

All current AD's & SB's complied with.

Fresh Annual inspection and ARC issue in completed mid November 2010.

This is an ideal opportunity to purchase this quality machine fitted with the highest standard furnishings.

Price: On Request

SkyTech Helicopters Ltd.

Tel: +44 (0) 1604 493137 E-mail: sales@skytechhelicopters.co.uk

Paint / Trim

Condition

Exterior: 10 / 10 Interior: 10 / 10

- Exterior Paint, New VIP Bell paint scheme in Black, Gold and Pearl White Metallic's.
- New corporate VIP interior consisting of deluxe seating in tan / black leather with piped edging.
- New replacement interior carpet in tan.
- New replacement interior trim panels.

Standard Equipment including the following:-

- Rolls Royce 250-C20 engine
- Collective Hobbs Meter
- Anti-collision light
- Fire Extinguisher

- 5 Seat Passenger Configuration
- Engine Anti-Ice
- Engine Wash Kit
- First Aid Kit

Installed Accessories

- High Skid Gear
- Rotorbrake
- Dual Controls
- Air Comm Corp Bleed Air Heater
- Raingutter Kit
- Pre Flight Maintenance Kits
- Paravion Cabin Door Actuators x 4
- Shoulder Harnesses
- Digital Chronometer
- Complete tie down / inlet kit

- Particle Separator
- Range Extender
- Lead Acid Battery
- New Windshields & Skylights
- New Rubber Mounted Wedge Windows
- New Rubber Mounted Chin Bubbles
- Baggage Door Strap / Opener
- Baggage Extender
- Cabin Floor Protectors

Avionic Suite

A comprehensive VFR avionic installation includes the following:-

- Collins APS-841H Autopilot
- Bendix/King KX 165 Nav / Com
- Bendix/King KT76A Trasnsponder
- Bendix/King KMA24H Audio Panel with 5 place intercomm
- Avionic Master Switch
- VSI

- Bendix/King KY 196A Com
- Bendix/King KCS-55 Compass System
- ACK A-30 Encoder
- Slant Instrument Console
- Attitude Indicator
- Turn & Bank Indicator

Specification subject to verification at inspection